

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H12SSW-AN6</b>
<b>Release Version</b>	<b>2.3</b>
<b>Release Date</b>	<b>10/01/2021</b>
<b>Build Date</b>	<b>10/01/2021</b>
<b>Previous Version</b>	<b>2.2</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>ECO #26026 BIOS Image: BIOS_H12SSWAN6-1C1F_20211001_2.3_STDsp.bin BIOS Update Package: BIOS_H12SSWAN6-1C1F_20211001_2.3_STDsp.zip Please update BIOS with attached Flash Utility in package.</b>
<b>Enhancements</b>	<b>1. Update Milan AGESA to 1.0.0.6 2. Update Rome AGESA to 1.0.0.C</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>N/A</b>

*Release Notes from Previous Release(s)*

**Revision 2.2 (2021/08/09)**

1. Followed the new cable plan to change the G1 & G2 PCIe config.
2. New AIOM card (AOC-A100G-m2CM) is Support; BIOS supports this AIOM card for BMC sensor reading.
3. When the AIOM1 changed device, the BMC gets a reset. However, it causes the BIOS cannot update the OOB file successfully.
4. Update BIOS version from 2.1 to 2.2
5. USB controller PCIe gen. speed fix from PCIe Gen. 1 to PCIe Gen. 2

**Revision 2.1 (2021/07/12)**

fixes the BIOS version shows incorrectly

**Revision 2.0 (2021/05/25)**

First release.