

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H12DSi-N6/NT6</b>
<b>Release Version</b>	<b>2.6</b>
<b>Release Date</b>	<b>4/13/2023</b>
<b>Previous Version</b>	<b>2.4</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>IPMI FW 1.01.25</b>
<b>Important Notes</b>	<b>BIOS Image: BIOS_H12DSI-1C22_20230413_2.6_STDsp.bin BIOS Update Package: BIOS_H12DSI-1C22_20230413_2.6_STDsp.zip</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Removed "Vendor Keys" on security page.</li><li>2. Modified String naming from SMCI to Supermicro.</li><li>3. Updated DBX file to fix Secure Boot Bypass issue.</li><li>4. Updated MilanPI to 1.0.0.A based on 5.22_MilanCrb_0ACOU021 for AMD-SB-1032.</li><li>5. Updated Milan B0/B1/B2 stepping CPU microcode and Milan-X B2 stepping CPU microcode to patch for Errata 1304, 1310, 1311, 1313, 1329, 1330, 1336, 1343, 1350, 1352, 1361, 1378,1379, 1381, 1386, 1407, 1433, 1450. B0 Milan microcode 0x0A001078, B1 Milan microcode 0x0A0011CE, B2 Milan-X microcode 0x0A001231.</li><li>6. Followed the SMBIOS template to sync the chassis type from FRU0 to SMBIOS Type 03 (only for H12 projects).</li><li>7. Updated AGESA RomePI to 1.0.0.F based on 5.14_RomeCrb_0ACMK026 for AMD-SB-1032.</li><li>8. Add FSRM and ERMSB items support. (Milan only, Rome not supported. PI 1009 changed default to enabled (Auto).</li><li>9. [SecurityErase] Modified GetVariable() service for buffer overflow in certain cases.</li></ol>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>N/A</b>

## ***Release Notes from Previous Release(s)***

### ***2.4 (4/22/2022)***

1. Changed BIOS revision to 2.4.
2. Added setup item, "ASPM Support" in PCIe/PCI/PnP Configuration Page.
3. Added "Factory Mode" function for Production test.
4. Updated AGESA RomePI to 1.0.0.D.
5. Updated Rome B0 stepping CPU microcode 0x08301055 to patch Errata 1161, 1176, 1179, 1183, 1214, 1268, 1386, 1417.
6. Updated AGESA MilanPI to 1.0.0.8.
7. Updated Milan B0/B1/B2 stepping CPU microcode and Milan-X B2 stepping CPU microcode to patch for Errata 1304, 1310, 1311, 1313, 1329, 1330, 1336, 1343, 1350, 1352, 1361, 1378, 1379, 1381, 1386, 1407, 1415.  
B0 Milan microcode 0x0A001058,  
B1 Milan microcode 0x0A001173,  
B2 Milan-X microcode 0x0A001229.
8. Added setup item, "SNP Memory (RMP Table) Coverage" and "Amount of Memory to Cover" in CPU Configuration Page.

### ***2.3 (10/21/2021)***

1. Changed BIOS revision to 2.3.
2. Updated AGESA RomePI to 1.0.0.C.
3. Exposed Setup item "Enhanced Preferred IO Mode".
4. Updated AGESA MilanPI to 1.0.0.6.
5. Patched case of BMC Redfish Host Interface being named ethX when CDN is disabled under Linux OS.
6. Disabled EFI iSCSI support.
7. Exposed Setup items "BankGroupSwapAlt", "SEV-SNP Support", "Enhanced Preferred IO Mode", and "Root Complex 0x00~0xE0 LCLK Frequency".
8. Changed default of "Wait For "F1" If Error" to Disable.
9. Updated B0 Milan microcode 0x0A00104C, B1 Milan microcode 0x0A001143, and B2 Milan-X microcode 0x0A001223 to patch Erratum #1381 problem of processor hanging when coherency probe hits instruction cache line while evicted.
10. Added Redfish/SUM Secure Boot feature and updated OOB for secure boot and reserve Key.
11. Added support for SUM upload/delete HTTPS TLS certificate (Default Enabled by TOKEN "Sum\_UploadTlsKey\_SUPPORT").
12. Set Relaxed Ordering default to Enabled.
13. Set all OPROM control items to Legacy when boot mode is set to Dual.
14. Removed legacy iSCSI support of H12 BIOS.
15. Added force next boot to UEFI Shell support.
16. Fixed missing sensor information on IPMI WebGUI.
17. Fixed problem of AFU being used to clear event log and then AC cycling the system after BIOS recovery.

### ***2.0 (4/09/2021)***

Initial Release