

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12STL-F
Release Version	1.8
Release Date	1/3/2024
Build Date	1/3/2024
Previous Version	1.6
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Updated BIOS version to 1.8.2. Updated AMI SA50216 Supplement for Security Advisory to address CVE-2023-39539 (7.5, High) security issue.3. SA50218 Supplement for update to fix seven exploitable security issues in the TianoCore EDK2 NetworkPkg integrated into AptioV. CVE-2023-45229 (6.5, Medium), CVE-2023-45230 (8.3, High), CVE-2023-45231 (6.5, Medium), CVE-2023-45232 (6.5, Medium), CVE-2023-45233 (6.5, Medium), CVE-2023-45234 (8.3, High), and CVE-2023-45235 (8.3, High).4. SA50230 Supplement to address CVE-2023-39539 (7.5, High) security issue.5. Updated Microcode A0671 to 0x5E and A0653 to 0xFA per IPU 2024.1.6. Updated SPS FW to 6.0.3.604 per IPU 2024.1.

	<ol style="list-style-type: none"> 7. Updated RC for IPU 2024.1 RC2124_50 PV. 8. Grayed out "Preferred DNS server IP" and "Alternative DNS server IP". 9. Added Rocky Linux into the BIOS default identical OS list.
New features	None
Fixes	<ol style="list-style-type: none"> 1. Fixed how a total HD capacity of more than 26T will cause incorrect BIOS menu HD information PBID:168341.

Release Notes from Previous Release(s)

1.6 (6/7/2023)

1. Update BIOS version to 1.6.
2. Updated Microcode A0653 to 0xf8 and A0671 to 0x59 per IPU 2023.3 Processor Advisory INTEL-TA-00828 to address CVE-2022-40982 (6.5 Medium).
3. Updated RC per IPU 2023.3 Processor Advisory.
4. Updated the SPS ME firmware to SPS_E3_06.00.03.505.0 per IPU 2023.3 Processor Advisory.
5. Updated the BMC/BMC Network Configuration page IPv6 DNS/DNS2 setting.
6. Added insert Secure boot key via SUM/Redfish.
7. Updated missing files of f3bb79b1ffb6a98bef254a236cace547f86f171c.

1.4a (03/06/2023)

1. Updated BIOS version to 1.4a.
2. Patch to fix the PCH chip that causes the USB OC problem.

1.4 (12/22/2022)

1. Updated BIOS version to 1.4.
2. Updated Microcode A0671 to 0x57 and A0653 to 0xF4 per IPU 2023.1 Processor Advisory INTEL-TA-00767 to address CVE-2022-38090 (6.0 Medium).
3. Updated ACM version to 1.14.46 (20220819) per IPU 2023.1 Processor Advisory INTEL-TA-00767 to address CVE-2022-30704 (7.2 High).
4. Updated the SPS ME firmware to SPS_E3_06.00.03.309.0 per IPU 2023.1 Processor Advisory INTEL-TA-00718 to address CVE-2022-36794 (6.0 Medium).
5. Updated EfiOsBootOptionNames and relevant dependencies for the Security update.
6. Modified the options of "Gen3 ASPM Control" and "Gen3 ASPM" match loading defaults by pressing F3.

1.2 (7/11/2022)

1. Applied a patch based on AMI Customer Advisory document UefiNetworkStack Aptio 5.x SA50110.

2. *Changed the text string "Security Erase Configuration" to "SMCI Security Erase Configuration."*
3. *Filtered the dynamic TCG security pages to patch the SUM ChangeBiosCfg failed problem.*
4. *Updated BIOS ACM and SINIT ACM to 1.14.39 (20211214) for 2022.1 IPU - BIOS Advisory. INTEL-TA-00601 addresses CVE-2021-33123 (8.2 High), CVE-2021-33124 (7.5 High) and CVE-2021-33103 (7.5 High).*
5. *Enabled SMBIOS chassis type to be the same as the FRU0 chassis type.*
6. *Changed the FRU0 chassis type to SMBIOS type 3 if it is not 1 or 2.*
7. *Updated AHCI driver from version 23 to version 28.*
8. *Enabled boot option for single HDD under RAID mode.*
9. *Updated Microcode to 0x54 per IPU 2022.2 Processor Advisory INTEL-TA-00657 to address CVE-2022-21233 (6.0 Medium).*
10. *Updated the root complex chipset with source code label 17 (5.22_1AXCT_RCOB.01.34.60_017).*
11. *Updated SMCOOB to 2.00.14.*
12. *Added the current boot device name in the SUM OOB configuration.*
13. *Fixed an error when an unknown device is installed and Intel® TXT is enabled.*
14. *Fixed the setup options of Enable Root Port, Max Link Speed, and ASPM of PEG Port Configuration.*
15. *Fixed the boot order displayed after using the AMIBCP tool.*
16. *Fixed the channel per DIMM displayed in the event log for DIMMB1.*

1.0a (11/18/2022)

1. *Added Intel PEG port width drop workaround and PEG port speed drop workaround.*
2. *Added Intel IPS #00641060 patch to support disabling of AVX/AVX3. Added AVX and AVX3 setup items.*
3. *Updated Microcode M02A0671_0000004C.*
4. *Added LAN1 and LAN2 Support items in PCIe/PCI/PnP Configuration.*
5. *Fixed an issue that when disabling BMC IPv6 Support in the BIOS, the IPv6 Address Status will show "Disabled" instead of "_".*
6. *Fixed system Recovery hang on 0x94 after BIOS crash under Dual mode.*
7. *Fixed serial number in SMBIOS type 17, as it loses bytes when using Samsung DDR4 memory.*
8. *Fixed SMCIPMITOOL/IPMICFG where it can't set persistent boot under DUAL mode, and Legacy mode through IPMI Boot Flag Command.*
9. *Fixed susceptibility to DDR4 Rowhammer attacks.*