

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRT-P(T)/PIBQ/PIBF
Release Version	3.90
Build Date	7/17/2020
Previous Version	3.86
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fixed failure of system to show as critical when PSU sensor is not plugged in.2. Fixed problem of destination address existing after FD.3. Corrected display of table when the Maintenance Event Log is full and the event log has "Activate_BIOS_Product_Key".4. Fixed failure to update BIOS function due to 3.87 firmware not supporting 2020 time format.5. Fixed ability to patch SSH Port to an already existing/default port value.

- | | |
|--|--|
| | <ul style="list-style-type: none">6. Fixed inability to patch Active Directory Role Group Domain with a period.7. Fixed mismatch of FRU value "13" Chassis Type between SMCIPMITool FRU and IPMI Web FRU.8. Fixed mismatch of FRU values "18" and "19" Chassis Type between SMCIPMITool FRU and IPMI Web FRU.9. Fixed problem of destination address existing after updating firmware by SMCIPMITool.10. Fixed problem of BMC web update flash firmware showing progress as 0%.11. Fixed issues with KVM console.12. Fixed problem of AOC SAS sensor disappearing from IPMI sensor reading.13. Fixed failure of the "PW consumption" to show on SNMP display. |
|--|--|