

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H11SSW-iN/NT (All)
Release Version	1.52.09
Release Date	12/10/2020
Previous Version	1.52.00
Update Category	Critical
Dependencies	N/A
Important Notes	ECO #24839 IPMI Image SMT_H11AST2500_32M_15209.bin Please update IPMI with attached Flash Utility in package.
Enhancements	Modify the Redfish PATCH method at "/Systems/1/Bios" and "/Systems/1/Bios/SD" to allow updating of BIOS attributes.
New features	N/A
Fixes	Power on system onboard buzzer still beep when after trigger thermal trip event

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

Revision 1.52.00 (11/18/2019)

- 1. System will not have any screen after flashing BIOS*
- 2. Issues on SPM REST API*
- 3. Improved ADMIN password is incorrect after reloading IPMI configuration*