

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSFR-AN6
Release Version	01.01.09
Release Date	2/15/2022
Previous Version	01.00.23
Update Category	Recommended
Dependencies	N/A
Important Notes	IPMI Image: BMC_H12AST2600-ROT-E201MS_20220215_01.01.09_STDsp.bin IPMI Update Package: BMC_H12AST2600-ROT-E201MS_20220215_01.01.09_STDsp.zip
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Sensor Reading UI Fail2. [MB Rev1.10] FAN sensor detection are wrong.3. [IPMI ECO v01.01.07] Remote Console Preview monitor function failed after press "Java plug-in" icon.4. [MB Rev1.10] Front panel's Fail LED is not blinking when fan pin got removed.5. [DVT]TDP Watts in IPMI Web GUI CPU information page is 06. [DVT]Unexpected duplicating FAN mode options7. SATC redfish test fail Copy Project Issue Link8. Duplicate Drives in IPMI WebGui9. STD -- 18380 -- 01.01.05 -- [SUM] TC239 BIOS password will not preserve after run sum command "LoadDefaultBiosCfg"10. STD -- 18380 -- 01.01.05 -- [redfish] version is mismatch with release note11. IPMIECO ATT test failed.12. GPU temperature display sequence is incorrect.13. [BMC 1.01.03] There's an abnormal event without description during AC cycles.

Release Notes from Previous Release(s)

01.00.23 (7/12/2021)

1. The Marvell controller(AOC-SLG2-2TM2) info and function are invalid in BMC WEB. Copy Project Issue Link
2. The AOC location info(AOC-AG-i2M) is N/A Copy Project Issue Link
3. The AOC location is not in sequence. Copy Project Issue Link
4. The sensor name"AIOM" under tab "Network AOC" is different from tab "Sensor" Copy Project Issue Link
5. Opening and closing the HTML5 Remote Console Disables Remote Console

01.00.08 (1/28/2021)

1. Digital Battery Reading Check Fail
2. No AIOM sensor reading on IPMI GUI.

01.00.00

First release.