

## BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11DPU-ZE+</b>
<b>Release Version</b>	<b>3.75.16</b>
<b>Release Date</b>	<b>01/05/2023</b>
<b>Previous Version</b>	<b>3.75.04</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. [IPMI ECO 03.75.13] SATC Redfish automation failed.</li><li>2. ECO – 14187 – 03.75.12(10/04/2022) – Can't display user account with special legal characters in the user list.</li><li>3. [AOC-CTG-b2T] No NIC sensors and MAC addresses are shown on WebGUI.</li><li>4. ECO –14187 – 03.75.13 (2022/10/27) – SUM – Auth access failed in some test cases.</li><li>5. IPMI automation has "User Name/Password verification failed."</li><li>6. ECO –14187 – 03.75.12 – An error message will pop up after canceling upgrade.</li><li>7. ECO –14187 – 03.75.12 – The behavior is incorrect after adding user name with "&lt;&gt;" characters.</li><li>8. ECO – 14187 – 03.75.12 – No error message when uploading an invalid TSIG key file and private file.</li></ol>

	<p>9. IPMI ECO Redfish Automation Tool Check has 4 fails.</p> <p>10. Prolonged execution time on VRM utility.</p>
New features	None
Fixes	<ol style="list-style-type: none"><li>1. [IPMI ECO v03.75.13] SATC Redfish automation failed.</li><li>2. [AOC-CTG-b2T] No NIC sensors and MAC addresses are shown on WebGUI.</li><li>3. ECO –14187 – 03.75.13 (2022/10/27) – WEB – MEL display updated successfully after uploading invalid SSL certification.</li><li>4. VRM utilities can be used on X11QPH+ when the battery is INSTALLED.</li><li>5. Hostname now supports special character "!", same as Web.</li><li>6. STD – SW–1.74.06 – Incorrect MEL when mounting an image failed</li><li>7. STD – SW–1.74.06 – Incorrect MEL when leaving the syslog server address blank.</li><li>8. STD – 17212 – 01.01.08 – Password goes wrong when it contains “\”.</li><li>9. STD – 1.72.12 – Unable to save valid domain name on AD page.</li></ol>