

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12DSi-N6/NT6
Release Version	1.01.24
Release Date	3/2/2023
Previous Version	1.01.13
Update Category	Recommended
Dependencies	BIOS 2.6
Important Notes	IPMI Image: BMC_H12AST2600-ROT-E201MS_20230302_01.01.24_STDsp.bin IPMI Update Package: BMC_H12AST2600-ROT-E201MS_20230302_01.01.24_STDsp.ZIP Note: If the IPMI firmware revision is earlier than 1.01.24, please do not select the “Preserve SDR” check box during IPMI firmware update.
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fixed issue of being unable to configure SNMPv1.2. Added AOC-S3816L-L16IR and AOC-S3808L-L8IR3. Removed I2c attack log4. Fixed issue of system reporting P1_VDDCR and P2_VDDCR voltage going high during cburn test5. Changed upper limit of SOCRUN and VDDCR.

Release Notes from Previous Release(s)

1.01.13 (4/27/2022)

1. Fixed: After inserting a S3916 RAID card, there is no event log generated, however IPMI dashboard is healthy but shows red.
2. Fixed: H12DSI-N6 => P2_VMEMABCD/P2_VMEMEFGH Sensor bug.
3. Set IPV6 factory default to 'enabled'.

1.00.26 (10/05/2021)

1. Corrected Memory FSC on MBD-H12DSI-N6-P.
2. Corrected CPU FSC on MBD_H12DSI-N6 for optimal and Heavy IO.

1.00.23 (6/17/2021)

1. Added support for Aspeed2600 chip A3.

1.00.19 (4/13/2021)

Initial Release