

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>X12DPi-N(T)6</b>  |
| <b>Release Version</b>  | <b>1.6 SPS: 4.4.4.500</b>  |
| <b>Build Date</b>       | <b>7/06/2023</b>   |
| <b>Previous Version</b> | <b>1.4b</b>  |
| <b>Update Category</b>  | <b>Recommended</b>   |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <ol style="list-style-type: none"><li><b>1. Changed version to 1.6.</b></li><li><b>2. Updated Intel BKC to 2023.3 IPU-PV(KIT#778442), RC.</b></li><li><b>3. Updated Intel BKC to 2023.3 IPU-PV(KIT#778442), SPS.</b></li><li><b>4. Updated Intel BKC to 2023.3 IPU-PV(KIT#778442), CPU 606A6 Microcode.</b></li><li><b>5. Updated Intel BKC to 2023.3 IPU-PV(KIT#778442), Intel VROC UEFI.</b></li></ol> |
| <b>New features</b>     | <b>None</b>  |
| <b>Fixes</b>            | <b>None</b>  |

## **Release Notes from Previous Release(s)**

### **1.4b (1/18/2023)**

1. *Changed version from 1.4a to 1.4b.*
2. *Fixed VMware issue.*
3. *Removed Setup item "eADR Support".*
4. *Grayed out CPU state controls when Power Technology is not Custom.*
5. *Removed Setup item "PCI AER Support".*
6. *Removed Setup item "Memory Corrected Error Enabling".*
7. *Removed Setup item "Factory Mode".*

### **1.4 (7/11/2022)**

1. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, RC.*
2. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, SPS.*
3. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, ACM.*
4. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, SINIT.*
5. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, CPU 606A6 Microcode.*
6. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, Intel VROC UEFI.*
7. *Update Intel BKC to 2022\_WW23(KIT #732569) PLR3, Intel PMEM UEFI.*
8. *Change version from 1.2a to 1.4.*
9. *Auto bifurcation for AOC-SLG3-2M2 on slot 6.*
10. *Fix Product Part/Model Number(PPM) issue.*
11. *Auto bifurcation.*
12. *Expose Link Retrain per port in BIOS.*

### **1.2a (5/12/2022)**

1. *Change version from 1.2 to 1.2a.*
2. *Improved UOL handle for BMC boot up timeouts.*
3. *Added KMS feature.*
4. *Fixed VMD issue. Fixed issue where the BIOS hangs at 79 when VMD is enabled.*
5. *Fixed Event log area length. Fixed issue with the length of event log area, which always shows 0.*
6. *Fixed NVRAM modifying limitation.*
7. *Fixed AC on/off DMI info mismatch.*
8. *Fixed the inability of the system to clean the Event Log.*
9. *Fixed issue where CPU1 does not appear.*

### **1.2 (01/26/2022)**

1. *Updated Intel BKC to 2021\_WW52 (KIT #709738), RC*
2. *Updated Intel BKC to 2021\_WW52 (KIT #709738), SPS*
3. *Updated Intel BKC to 2021\_WW52 (KIT #709738), ACM*
4. *Updated Intel BKC to 2021\_WW52 (KIT #709738), SINIT*
5. *Updated Intel BKC to 2021\_WW52 (KIT #709738), CPU 606A6 Microcode*
6. *Updated Intel BKC to 2021\_WW52 (KIT #709738), Intel VROC UEFI*
7. *Updated Intel BKC to 2021\_WW52 (KIT #709738), Intel PMEM UEFI*

### **1.1c (08/30/2021)**

1. Updated the Intel BKC to 2021\_WW32 (KIT #645801), RC, Intel update to BKC to fix general platform issues.
2. Updated the Intel BKC to 2021\_WW32 (KIT #645801), SPS, Intel update to BKC to fix general platform issues.
3. Updated the Intel BKC to 2021\_WW32 (KIT #645801), ACM, Intel update to BKC to fix general platform issues.
4. Updated the Intel BKC to 2021\_WW32 (KIT #645801), SINIT, Intel update to BKC to fix general platform issues.
5. Updated the Intel BKC to 2021\_WW32 (KIT #645801), CPU 606A6 Microcode, Intel update to BKC to fix general platform issues.
6. Updated the Intel BKC to 2021\_WW32 (KIT #645801), Intel VROC UEFI, Intel update to BKC to fix general platform issues.

### **1.1b (7/20/2021)**

1. Reworked UOL to remove MAC from Type 42.

Reworked BIOS Template to conform to version 1.0 of the Whitley template.

### **1.1a (6/25/2021)**

1. Updated Intel BKC to 2021\_WW24 (KIT #642595), RC.
2. Updated Intel BKC to 2021\_WW24 (KIT #642595), SPS.
3. Updated Intel BKC to 2021\_WW24 (KIT #642595), ACM.
4. Updated Intel BKC to 2021\_WW24 (KIT #642595), SINIT.
5. Updated Intel BKC to 2021\_WW24 (KIT #642595), CPU 606A6 Microcode.
6. Reworked BIOS Template to match version 1.0.
7. Reworked SUM support.
8. Incremented the Anti-Rollback ID to 2.
9. Fixed PB issues.

### **1.1 (4/21/2021)**

1. Updated Intel BKC to WW15'21 (PV), RC.
2. Updated Intel BKC to WW15'21 (PV), SPS.
3. Updated Intel BKC to WW15'21 (PV), 606A4 Microcode.
4. Updated Intel BKC to WW15'21 (PV), 606A5 Microcode.
5. Updated Intel BKC to WW15'21 (PV), 606A6 Microcode.
6. Updated Intel BKC to WW15'21 (PV), BIOS ACM.
7. Updated Intel BKC to WW15'21 (PV), SINIT ACM.
8. Updated Intel BKC to WW15'21 (PV), NVDIMM UEFI HII.
9. Update Intel BKC to WW15'21 (PV), VMD VROC.
10. Reworked BIOS Template to match version 0.9.
11. Reworked SUM Support.
12. Implemented Unique FW Name in OEMFID.
13. Implemented Redfish Boot Options.
14. Implemented Intel Optane DCPMM FW Update.
15. Fixed PB issues.

### **1.0a (12/28/2020)**

1. Updated Intel BKC to WW51'20.
2. Reworked BIOS template to match version 0.8.
3. Reworked MCTP.

### **1.0 (10/30/2020)**

Initial release.

|  |
|--|
|  |
|--|

---

*Product Manager*

---

*Date*