

BMC FW Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPU-6
Release Version	1.03.10
Build Date	12/3/2023
Previous Version	1.03.07
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none">SUM Test case fails: 0030 - Ping BMC IP from SUT with a different LAN interface.The Severity display with improper Blue color code happened for MEL "ejected unsuccessfully".WEB – Needed to define MEL-ID for modified IPv6 address/Prefix Length.BMC 01.03.07 duplicate MEL message when enabling IPv6 in WebGUI.[IPMI ECO 01.03.07] UID LED should be blinking but keep solid on when using WebUI UID Control.Host Interface only supports RNDIS on the release note and Help page but web appear CDC-ECM and RNDIS.