BIOS Release Notes Form

Product Name	**X12DSC-6**
Release Version	**1.2 SPS: 4.4.4.62**
Build Date	**3/5/2022**
Previous Version	**1.1a**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	1. **Updated AMI 5.22_WhitleyCrb_0ACMS_ICX_070 RC27P56 to BKC 2021_WW52 (PLR1 HF).** 2. **Added flag [Preserve BIOS Boot Options Configuration] controlled by BMC/SUM.** 3. **Changed string "VMX" to "Intel Virtualization Technology".** 4. **Change BIOS revision to 1.2.**
New features	**N/A**
Fixes	1. **Removed 1G option from MMCFG base to avoid system hang.** 2. **Fixed the SMBIOS event log ERROR CODE which is not displaying correctly under BIOS menu issue (EFI error type).** 3. **Fixed SpeedStep (P-States) setting, changed when its default setting is set to Disable, and load BIOS defaults in Setup.** 4. **Fixed COM port resource that can't be changed and item's behavior failure.**

1.1a (7/21/2021)

1. *Updated 5.22_WhitleyCrb_0ACMS_ICX_066_BETA Intel BKCWW24 2021 PV MR4.*
2. *Updated Dx/Mx microcode from Intel-Generic-Microcode-20210701_NDA.*
3. *Updated SmcOOB module to 1.01.24 to support SUM clean SMBIOS Event log through BiosCfg header flag.*
4. *Corrected firmware version and vendor on Trusted Computing page.*