IPMI Firmware / BIOS Release Notes Form

Product Name	**H12SSW-AN6**
Release Version	**1.01.14**
Release Date	**07/01/2022**
Previous Version	**1.01.11**
Update Category	**Critical**
Dependencies	**N/A**
Important Notes	**ECO #26969** **BMC_H12AST2600-ROT-E201MS_20220701_01.01.14_STDsp.bin** **Please update IPMI with attached Flash Utility in package.**
Enhancements	Factory Default enables IPv6
New features	N/A
Fixes	N/A

1.01.11(2022/03/16)
1. support AOC-S3816L-L16IT-O shown the AOC /HDD Temp in sensor reading via IPMI Web GUI
2. Support AOC-3908 shown the sensor reading via IPMI Web GUI

1.00.26(2021/10/05)
1. Fixed the BIOS golden image update failed issue.

1.00.23 (06/16/2021)
1. Fixes when system power on, IPMI GUI power control status still show red.
2. [PB#126433] fixes the AOC location is not in sequence.
3. [PB#126783] There is BMC SEL "Dedicated LAN Link Down - Assertion" during AC cycle stress.
4. [PB#125637] fixes the IPMI web can not read AIOM NIC temperature
5. [PB#122813] fixes the sensor name "AIOM" under tab "Network AOC" is different from tab "Sensor" Copy Project Issue Link
6. [PB#128391] fixes the AOC location info. (AOC-AG-i2M) is N/A Copy Project Issue Link
7. [PB#128412] fixes the Marvell controller (AOC-SLG2-2TM2) info and function are invalid in BMC WEB

1.00.20 (5/12/2021) First release