# IPMI Firmware Release Notes Form

| | |
|---|---|
| **Product Name** | **H12DGQ-NT6** |
| **Release Version** | **1.01.24** |
| **Build Date** | **03/02/2023** |
| **Previous Version** | **1.01.16** |
| **Update Category** | **Recommended** |
| **Dependencies** | |
| **Important Notes** | **ECO#27912**<br>**IPMI image: BMC_H12AST2600-ROT-E201MS_20230302_01.01.24_STDsp.bin**<br>**IPMI Update package: BMC_H12AST2600-ROT-E201MS_20230302_01.01.24_STDsp.zip** |
| **Enhancements** | **N/A** |
| **New features** | **N/A** |
| **Fixes** | **1. Added asterisks ("*") to all required fields on the website (Directory Service)**<br>**2. Fixed the issue where no entries of inputting symbol values could be found in MEL Log.**<br>**3. Fixed the issue of when radndom IPMI sensor readings failed, all sensors showed N/A.** |

**1.01.16 (08/05/2022)**
1. Fixed: Couldn't change LAN config with static IP.


**1.01.13 (04/27/2022)**
1. Fixed issue where the PSU FAN can't be controlled by the IPMI FAN page.
2. Modified function to get MI250 GPU device ID.
3. Enabled IPv6 by factory default.


**1.01.09 (02/15/2022)**
First release.