BMC Firmware Release Notes

Product Name	**X13DEG-PVC**
Release Version	**1.00.03**
Build Date	**10/15/2023**
Previous Version	**Beta Release**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	1. **HTML5 Console as default.**
New features	1. **Displayed numeric sensors of OAM on webpage.**
Fixes	1. **Fixed the problem where the link speed of the BMC dedicated LAN might become 10M Half when the configuration is set to Auto.** 2. **Samsung NVME (HDS-SUN0-MZWLO1T9HCJA07) disk info was not shown correctly under BMC GUI.** 3. **MCX75310AAS-NEAT (slot 6 to slot 8) "health status" shown as grayed out under BMC GUI.** 4. **Fixed updating GPU failure but without exiting the update mode issue.**

	5. Front panel LED behavior incorrect after executing CPU overheat Copy Project Issue Link. Both "Information LED" and "Power Fail LED" are blinking 1Hz when Fan failure. Front panel 6-LED (Power fail LED) can't "stays solid RED" after pulling out power cable Copy Project Issue Link. 6. [Webpage][PSU] Fixed 'AC Input Current' and 'AC Input Current' incorrect issues. 7. Motherboard 2nd CPLD text is blocked by an icon. 8. Changed default fan mode to 'Optimal Speed' * Need factory reset.