IPMI Release Notes

Product Name	**X12SPW-(T)F**
Release Version	**01.03.11**
Build Date	**12/20/2023**
Previous Version	**01.03.08**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	**None**
New features	**N/A**
Fixes	1. **MEL Log message is incorrect when ONLY enable/disable Radius.** 2. **Supposed to show ONLY the least required key of the limited function when no License is activated.** 3. **DNS Lookup toggle button and Host interface radio buttons aren't disabled when system lockdown mode is on.**

4. Help page should show CDC-ECM and RNDIS options for Host Interface.

5. Irrelevant MEL when setting up Hostname.

6. Host Interface page can be configurated in system lockdown mode or login with User privilege.

7. No related MEL generated after SMTP sender's address is removed.

8. -- SMCIPMITool -- [MEL-0000]/[MEL-0002] has 2 spaces before the Username.

9. Able to add ACCEPT/DROP rules with duplicate IP Address/Mask.

10. After Web BMC Update, MEL Maintenance Event Log does not contain entry stating that BMC firmware was updated successfully.

11. Slot number does not match spec under BMC Web GUI.

12. SUM Test case fails: 0030 - Ping BMC IP from SUT with different LAN interface.

13. Failed to delete Active Directory Domain Name.

14. Failed to edit/delete Active Directory Server Address.

15. The tips of Remote User and Remote Group are different from the specifications.

16. Added MEL-ID for modified IPv6 address/Prefix Length.

17. No LLDP introduction at Help page.

18. Duplicate MEL message when enabling IPv6 in WebGUI.

19. iKVM Reset modal buttons show "Close" and "OK" instead of Yes and No even though it asks "Are you sure you want to RESET the iKVM?"

20. Fixed message "Please enable one directory service at a time !" should remove the extra space.

21. Failed to delete the search base in the LDAP Configuration.

22. Search base display "ISNULL" after the data has been removed.