IPMI Firmware

Product Name	**X10SRH-CF/CLN4F**
Release Version	**3.65**
Release Date	**12/15/2017**
Previous Version	**3.58**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	**1. Improved multi-language content on the iKVM/HTML5 option menu and submenu.** **2. Disabled MCTP support on Broadcom 3108 firmware so it only supports I2C protocol.**
New features	**N/A**
Fixes	**1. Fixed failure of SUM 2.0.1 Test.** **2. Fixed failure of SUM "Test_case_215 Outband - ChangeBmcCfg and compare".** **3. Fixed inability to disable LDAP Authentication immediately after enabling it.** **4. Fixed problem of product serial number being incorrect when it is longer than 15 characters and written in IPMI FRU.**