

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>BH12SSi-M25</b>
<b>Release Version</b>	<b>1.0a</b>
<b>Release Date</b>	<b>06/16/2020</b>
<b>Previous Version</b>	<b>1.0</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>BIOS Image: BH12SSi0.616 BIOS Update Package: BH12SSi0.616.ZIP</b>
<b>Enhancements</b>	<b>1. Change BIOS revision to 1.0a. 2. Update AGESA RomePI to 1.0.0.7. 3. Update 8310 SSP-B2 microcode 8301038. 4. Fixed USB doesn't work on IPMI GUI. 5. Auto update P1 slot bifurcation and SATA mode.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>N/A</b>

### Release Notes from Previous Release(s)

<b>1.0 (05/04/2020)</b>  First release.
---