

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSFF-AN6
Release Version	2.0
Release Date	02/23/2021
Build Date	02/23/2021
Previous Version	1.b
Update Category	Critical
Dependencies	N/A
Important Notes	BIOS Image: BIOS_H12SSFF-1C19_20210223_2.0_STDsp.bin BIOS image and flash utility package: B BIOS_H12SSFF-1C19_20210223_2.0_STDsp.zip Notice: 1) BIOS R2.0 support 7002 and next generation processor. 2) Flash Utility in package supports BIOS R1.x update to R2.x only, cannot roll back.
Enhancements	1. Changed BIOS revision to 2.0. 2. Added support for both AMD EPYC 7002 and next generation processors. 3. Updated A011 GN B1 microcode 0A001119. 4. Updated AGESA RomePI to 1.0.0.A. 5. Fixed problem of BIOS initialization showing IPV6 address when IPV6 is disabled in the IPMI GUI. 6. Enhanced SMBIOS Type39 System Power Supply information.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

1.0b (2021/01/28)

1. Reaction to BMC 00.01.25, BMC remove the reset from a changing LAN data within the 30/20 command. BIOS remove the patch.

1.0a (2020/12/19)

1. Changed BIOS revision to 1.0a
2. Patched problem of POST randomly hanging at B2 during AC aging.
3. Corrected OEM FID VBIOS version.

1.0 (2020/12/14)

Initial release.