

## BMC Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>C9X299-(R)PGF</b>
<b>Release Version</b>	<b>1.31.04</b>
<b>Build Date</b>	<b>1/20/2021</b>
<b>Previous Version</b>	<b>1.31.02</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>1. Enabled CSRF feature. 2. Adjusted low fan threshold to 200, 300, and 500 RPM.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Fixed issue with add-on card thermal reading. 2. Corrected error message from 'User name must be 4~16 characters.' To 'User name must be 4~15 characters.' 3. Corrected typo in SSL Certification confirm window. 4. Fixed problem of user being permanently locked out after exceeding lockout times by SMCIPMITool.</b>

**Release Notes from Previous Release(s)**

**1.25 (8/29/2018)**

1. Improved multi-language content on the iKVM/HTML5 option menu and submenu.
2. Improved the help message descriptions to follow Help Menu Suggestions v1.8.
3. Added support for C9X299-PGF.
4. Fixed inability of IPMI to show System Event Log.
5. Fixed abnormal VCPU reading (UNR).
6. Fixed missing 3108 sensor reading in WebGUI.
7. Fixed ability of IPMI Web to detect user if user is deleted through SMCIPMITool.
8. Fixed missing IPMI sensor after disabling "IPMI Extended Instruction".
9. Fixed missing default timeout value on Redfish when accessing Manager's ActiveDirectory.
10. Fixed inability to patch IP Access Enabled key with 500 Internal Error on Redfish.
11. Fixed missing "Thermal Trip" event in IPMI SEL.