

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SRi-IF
Release Version	2.4
Release Date	1/29/2021
Build Date	1/29/2021
Previous Version	2.2
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Upgraded Skylake W U-0 microcode to version 6A09. 2. Upgraded Cascade Lake W B-0 microcode to version 3005. 3. Upgraded Cascade Lake W L-1 microcode to version 3005. 4. Upgraded ME to 11.12.82.1838. 5. Updated Intel RC to 2374.D00.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

2.2 (9/3/2020)

1. Updated version to 2.2.
2. Fixed issue of BIOS hanging during postcode 99.
3. Updated ME to 11.12.79.1722.
4. Added SUM v1.8 Flags with block SUM OOB update.
5. Fixed issue of BIOS hanging indefinitely during OOB upload.
6. Updated RC to 1524.D00.
7. Upgraded Skylake W U-0 Microcode to Version 6906.
8. Upgraded Cascade Lake W B-0 Microcode to Version 2F01.
9. Upgraded Cascade Lake W L-1 Microcode to Version 2F01.
10. Upgraded ME to 11.12.77.1664.
11. Added HDD Secure Erase function.

2.0a (12/19/2019)

1. Updated Intel RC to 1464.D01.
2. Updated SINIT ACM to 1.3.54.
3. Updated SATA RAID UEFI to 6.2.0.1034.
4. Enabled AFU to clear event log properly without causing a system crash.

2.0 (11/26/2019)

1. Fixed BIOS Rescue.
2. Fixed AMI DMIEdit.
3. Changed OEM String to Glacier Falls.
4. Upgraded Skylake W U-0 Microcode to Version 65.
5. Added Cascade Lake W L-0 Microcode Version 2C.
6. Added Cascade Lake W L-1 Microcode Version 2C.
7. Upgraded Code Base to Glacier Falls WS RC 1352.D01.
8. Upgraded Skylake W U-0 Microcode to Version 64.
9. Added Cascade Lake W A-0 Microcode Version 10.
10. Added Cascade Lake W B-0 Microcode Version 2B.
11. Added Cascade Lake W L-1 Microcode Version 2B.
12. Upgraded BIOS version to 2.0.
13. Removed support for CPUID 50652.
14. Added support for OOB BIOS Flash.