

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12SPW</b>
<b>Release Version</b>	<b>1.1</b>
<b>Release Date</b>	<b>4/9/2021</b>
<b>Build Date</b>	<b>4/9/2021</b>
<b>Previous Version</b>	<b>1.0a</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated RC 20.P95 for PV RC update.</li><li>2. Updated SPS 4.4.4.53.</li><li>3. Updated Intel-Generic-Microcode-20210226a_NDA and Intel AE.</li><li>4. Corrected BIOS version that shows in IPMI after ROT recovery of previous version of BIOS.</li><li>5. Added support for VROC OOB.</li><li>6. Removed iSCSI option from LAN OPROM item.</li><li>7. Set PCH PCIe ASPM to disabled if CPU PCIe global ASPM is disabled.</li><li>8. Changed "SMCI PMem Formset" to "SMCI PMem Configuration".</li></ol>
<b>New features</b>	<b>N/A</b>

<b>Fixes</b>	<ol style="list-style-type: none"><li data-bbox="488 149 1235 184">1. Corrected memory device number in SMBIOS type 16.</li><li data-bbox="488 207 1013 243">2. Fixed problem with a CPU exception.</li><li data-bbox="488 266 1386 352">3. Fixed problem of T-states always showing 15 levels even when T-state is disabled.</li></ol>
--------------	---

## **Release Notes from Previous Release(s)**

### **1.0a (3/5/2021)**

1. Updated 5.22\_WhitleyCrb\_OACMS\_ICX\_058\_BETA for PC2 RC update.
2. Updated BIOS ACM 1.0.9 and SINIT ACM 1.0.9.
3. Updated SPS 4.4.51.
4. Fixed inability of the system to boot into PXE with DVD installed.
5. Kept setup string of BiosVersion, BiosDate, Manufacturer, and Product as default value including modification of AmiBcp.
6. Kept value of setup string of Manufacturer and Product according to priority "modification of AmiBcp, FUR1, and then SMBIOS Table".
7. Updated Intel-Generic-Microcode-20210226a\_NDA and Intel AE.
8. Automatically disabled and hid ADDDC with x8 width DIMM.
9. Extended memory DIMM serial number information (Samsung, Micron, Hynix).
10. Enhanced SMC DCPMM feature.
11. Automatically disabled and grayed out ADDDC, UMA-Base Clustering, and mirror mode and enabled NUMA when SGX is enabled.
12. Set relation setup to restore setting after "Factory Mode" is disabled.
13. Removed 4G limit of Intel LAN memory if boot mode is not legacy.
14. Set all OPROM control items to Legacy when boot mode is set to Dual.
15. Updated SATA/sSATA EFI driver to VROC PreOS v7.5.0.1152.
16. Updated BPS firmware to 2.2.0.1553.
17. Set BootGuard to enabled by default.
18. Fixed problem of "Configuration Address Source" always showing "DHCP" on IPMI IPv6 page.
19. Modified IPv6 behavior and removed error message when IPv6 router IP is :::::.
20. Corrected display of IPv6 status after updating BIOS.
21. Corrected display of IPv4 address source status after updating BIOS.
22. Prevented failure of Redfish check items using items with same SGX\_PROMPT Name and different offset.
23. Fixed problem of BIOS initialization showing IPV6 address when IPV6 is disabled in the IPMI GUI.
24. Filtered Dynamic HDD Security pages to patch failure of SUM ChangeBiosCfg.
25. Set AFU to stop if there are no parameters.
26. Fixed mismatch of memory device in IPMI and in BIOS setup when some memory DIMMs are mapped out.
27. Corrected display of IPv6 when IPv6 status is not active.
28. Fixed inability to upload all OOB files on the first BMC boot.
29. Fixed failure of Secure Boot Append/Update Keys.
30. Corrected display of UEFI OS boot option name in BIOS setup.
31. Corrected SMBIOS Type 41 onboard VGA description string to AST2600.
32. Fixed failure of SUT to prompt "Enter User password" screen after setting a password when plugging in SED device.
33. Fixed failure of the HDD security menu to show when more than 6 HDDs are connected on system.
34. Fixed inability of AOC NVMe card to change to VMD mode when setting NVMe switch to VMD.

