

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H12DGO-6</b>
<b>Release Version</b>	<b>2.0c</b>
<b>Release Date</b>	<b>06/03/2021</b>
<b>Build Date</b>	<b>06/03/2021</b>
<b>Previous Version</b>	<b>2.0b</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>IPMI firmware 1.00.34</b>
<b>Important Notes</b>	<b>ECO #25341</b> <b>BIOS image: BIOS_H12DGO6-1C1E_20210603_2.0c_STDsp.bin</b> <b>BIOS Update package: BIOS_H12DGO6-1C1E_20210603_2.0c_STDsp.zip</b> <b>Notice:</b> <b>1) BIOS R2.x supports 7002 and 7003 processor.</b> <b>2) Flash Utility in package supports BIOS R1.x update to R2.x only, cannot roll back.</b> <b>3) R2.x BIOS default boot mode has been changed to EFI. If your OS is legacy, please press Del during POST to enter into BIOS setting page to change boot mode after upgrade to R2.x.</b>
<b>Enhancements</b>	<b>1. Changed BIOS revision to 2.0c.</b> <b>2. Modified UEFI shell boot order ahead of AIOM PXE with Milan CPU.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Fixed PCIE Gen drop issue on PLX switch downstream ports.</b>

## ***Release Notes from Previous Release(s)***

### **2.0b (05/24/2021)**

1. Changed BIOS revision to 2.0b.
2. Added CPU and NB menus to SUM setup template.
3. Updated Rome/Milan AGESA code to 1.0.0.A/1.0.0.1.
4. Added delay in reading PSU FRU through BMC.
5. Changed system onboard slot number to 11.
6. Added a patch to solve NVidia-smi GPU loss issue with Intel NIC installed on switch board.
7. Added a workaround to assign 32bit resource for AIOM NICs to support legacy PXE.
8. Applied BIOS setup settings pushed by SUM without entering BIOS setup.
9. Changed PCIe port PMEM size.
10. Added support for unique filename.
11. Improved UOL data transfer between BIOS to BMC.
12. Corrected help strings in PCIe/PCI/PNP configuration page.

### **2.0a (03/25/2021)**

13. Changed BIOS revision to 2.0a.
14. Removed unused SATA ports in BIOS setup.
15. Updated SMBIOS TYPE 9 and 40 table.
16. Treated AIOM as onboard NIC.

### **2.0 (03/04/2021)**

17. Changed BIOS revision to 2.0.
18. Added support for both AMD EPYC 7002 and next generation processors.
19. Added support for Nvidia A100 80G GPU.
20. Improved SMBIOS Type 39 PSU reading procedure.
21. Added xGMI setup options.
22. Fixed problem of NVMe hot-swap resetting the system.
23. Fixed inability to enable ECC reporting by Cburn.

### **1.0a (12/10/2020)**

1. Changed BIOS revision to 1.0a.
2. Provided all of AIOM NIC MAC addresses to BMC.
3. Fixed issue of CPU2 dropping.

### **1.0 (11/13/2020)**

First release.

