

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>X12DPG-AR</b>   |
| <b>Release Version</b>  | <b>1.2 SPS: 4.4.4.62</b>   |
| <b>Build Date</b>       | <b>01/22/2022</b>  |
| <b>Previous Version</b> | <b>1.1a</b>  |
| <b>Update Category</b>  | <b>Recommended</b>   |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <ol style="list-style-type: none"><li>1. Intel update BKC to fix general platform issues. RC is updated to 27.P52.</li><li>2. Intel update BKC to fix general platform issues. SPS is updated to 4.4.4.62.</li><li>3. Intel update BKC to fix general platform issues. ACM is updated to 1.0.Eh.</li><li>4. Intel update BKC to fix general platform issues. SINIT is updated to 1.0.Fh.</li><li>5. Intel update BKC to fix general platform issues. CPU 606A6 Microcode is updated to 0D000331.</li><li>6. Intel update BKC to fix general platform issues. Intel VROC UEFI is updated to 7.7.0.1054.</li><li>7. Intel update BKC to fix general platform issues. Intel PMEM UEFI is updated to 2.0.0.3885.</li></ol> |
| <b>New features</b>     | <b>N/A</b>   |
| <b>Fixes</b>            | <b>N/A</b>   |

