

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPD-A6M25
Release Version	1.4a SPS: 4.4.4.301
Build Date	11/24/2022
Previous Version	1.1
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Updated 5.22_WhitleyCrb_0ACMS_ICX_73 Intel BKCWW40 PLR3 OOB. Please check header for firmware revisions.2. Updated VROC SATA/sSATA EFI driver to VROC PreOS v7.8.0.1012 to address Intel Virtual RAID on CPU (VROC): Data Loss Exposure Due to RAID 5 TRIM Support document #7372763. Added "CSM Support" setup item into SM CISBForm page.4. Filter Dynamic TCG Security Pages to patch SUM ChangeBiosCfg failed problem5. Enhanced get VPD data routines for E810.6. Supports IPMI PXE boot to all LAN port feature for both Legacy and UEFI PXE.7. Applied workaround to fix Linux OS show incorrect CPU max freq issue.8. Updated SmcOOB to the version "_SMCOOBV1.01.25_" to fix the unexpected system-reseting when loading NVRAM defaults.9. Exposed Link Retrain per port, exposed MCTP for CPU1 slot1 and CPU2 slot2 in BIOS.10. If chassis type of FRU0 is not 1(other) or 2(unknown), sync it to SMBIOS type 3.11. Updated Intel Server Platform Services for Whitley Server Platforms IPU2023.1 4.4.4.301
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fixed SUM ChangeBiosCfg command cannot update PchSetup variable related BIOS items issue.

1.1 (5/7/2021)

1. *Set default Boot Guard profile to 5.*
2. *Updated Intel BKCWW17 2021 PV MR1.*
3. *Set all OPROM control items to Legacy when boot mode is set to Dual.*
4. *Updated CPLD Signature table 101 and tool to 1.30.24 for CPLD Signature.*
5. *Extended memory DIMM serial number information (Samsung, Micron, Hynix).*
6. *Fixed problem of T-states always showing 15 levels even when T-state is disabled.*
7. *Fixed missing offboard output in Setup if limited to 4G in Non-EFI mode.*
8. *Fixed failure of Microsoft HLK certification and TPM 2.0 UEFI Preboot Interface Test on Microsoft Server 2019.*
9. *Fixed problem with a CPU exception.*
10. *Fixed failure to hide the SmcSecureErase setup page when no HDD devices are plugged in.*
11. *Corrected display of UEFI OS boot option name in BIOS setup.*
12. *Fixed failure of Secure Boot Append/Update Keys.*
13. *Fixed inability to upload all OOB files on the first BMC boot.*
14. *Corrected memory device number in SMBIOS type 16.*
15. *Corrected iSCSI Configuration page.*
16. *Set DIMM size to recalibrate when rank is disabled.*
17. *Fixed the issue of system hanging after executing `sum -c EraseOAKey` or `afuefi /OAD`.*