

## BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>X13DET-B</b>  |
| <b>Release Version</b>  | <b>1.00.34</b>   |
| <b>Build Date</b>       | <b>3/27/2023</b>   |
| <b>Previous Version</b> | <b>1.00.31</b>   |
| <b>Update Category</b>  | <b>Recommended</b>   |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <b>None</b>  |
| <b>New features</b>     | <ol style="list-style-type: none"><li>1. Added support for Motherboard CPLD Golden Image Version Display.</li><li>2. Added support for Motherboard CPLD Golden Image Update.</li></ol>   |
| <b>Fixes</b>            | <ol style="list-style-type: none"><li>1. Failed to update SAS3808.</li><li>2. Fixed incorrect node names in WebGUI Smart Power Page.</li><li>3. Modified the data length check of the OOB preserve command: 0x30 0xA0 0x15.</li><li>4. Corrected UUID format.</li><li>5. Fix the issue of too much fan noise when the system is OFF.</li></ol> |