

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H11SSL-i/C/NC (2.0)
Release Version	1.52.21
Release Date	09/26/2023
Previous Version	1.52.15
Update Category	Recommend
Dependencies	N/A
Important Notes	ECO #28788 BMC_H11AST2500_6101MS_20230926_01.52.21_STDsp.bin Please update IPMI with attached Flash Utility in package.
Enhancements	N/A
New features	N/A
Fixes	1. [security] "IPMI configuration backup file remote command execution 2. [Security] Vulnerable JavaScript library prototypejs v1.5.0 at X11 [Security] Vulnerable JavaScript library jquery-ui v1.11.4 at X11 Vulnerable JavaScript library bootstrap v3.2.0 at X11

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

Revision 1.52.15 (11/08/2021)

DIMM drop occurred after the DC on/off test.

Revision 1.52.12 (03/11/2021)

- 1. Improve BMC's access to the system SMBus (DIMM drop when the system is reset).*
- 2. Fixes when fail to set user name with special characters thru SMCIPMITool*

Revision 1.52.00 (11/18/2019)

- 1. System will not have any screen after flashing BIOS*
- 2. Issues on SPM REST API*
- 3. Improved ADMIN password is incorrect after reloading IPMI configuration*