

## BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

<b>Product Name</b>	<b>X13SEI-F/TF</b>
<b>Release Version</b>	<b>1.01.08</b>
<b>Build Date</b>	<b>11/5/23</b>
<b>Previous Version</b>	<b>1.00.58</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. HTML5 Console as default.</li><li>2. Dual mode for network setting as default.</li><li>3. Virtual media now supports three CD/FLOPPY image mounting.</li><li>4. Modified Dedicated Link options: Added 1G Full and removed 10M Half/Full. Exception: The dedicated link of X12STD-F, X12STE-F and M13SRD-F was fixed in Auto Negotiation. The dedicated link of X12DPG_U6 was fixed in 100M Full.</li><li>5. After CPLD firmware updates using the webUI, system should auto power-on.</li></ol>
<b>New features</b>	<ol style="list-style-type: none"><li>1. Redfish now supports new OEM Fixed Boot Order API to replace Boot Order for change BIOS boot option.</li><li>2. Disabled IPMI Lan Port interface.</li></ol>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Corrected Redfish failed sensor reading.</li></ol>