

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13SCW
Release Version	1.1
Release Date	12/07/2023
Build Date	12/07/2023
Previous Version	1.0
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. [BKCWW41] Updated Microcode 0xB0671 to 0x11F and 90672 to 0x34 per Intel Catlow BKC WW41.2. [WW39] Upgraded SPS Tool version and FW from MFit_SPS_E3_06.02.04.006.0_kn3 to MFit_SPS_E3_06.02.04.008.0_kn3.3. Fine tune get VPD data routines delay to avoid system trigger w/a and keep rebooting.4. "System Mode: Deployed" was not displayed as expected when enabling Secure Boot.5. Updated the Intel MRC to 0C.00.6B.41 per Intel Catlow BKC WW41. (3384.00)6. Updated the SUM OOB module to SMCOOBV2.00.21 to support Redfish replace the display name feature.

	<ul style="list-style-type: none"> 7. Enhanced the FixedBootOrder module to let the FixedBootOrder function show in the Redfish page. 8. Added BIOS setup keyword search function. 9. Grayed out "Preferred DNS server IP" and "Alternative DNS server IP". 10. The Intel RSTe name was removed and all RAID solutions in this product were branded as Intel VROC. 11. Updated Intel Gigabit Lan driver to 9.8.09 (IBA 27.6). 12. Fixed System - PNP (disable and enable) with IO. 13. Implemented Anti roll back for OOB that could not power on after roll back ME. 14. Triggered PERR SMBIOS Type 15 log will change the root port bridge to End-Device BDF.
<p>New features</p>	<p>None</p>
<p>Fixes</p>	<ul style="list-style-type: none"> 1. Added when enable PCH PCIe swap function, and system reset the Early Video function can't be worked. (Default disable) 2. SMBIOS Type 04 CPU current speed set the non-turbo mode. 3. Fixed ME status will enter recovery mode when flashing the BIOS via afuefix64.efi. 4. [SmcUefiBootsOptionRedfish] Made sure to assign unique ID for NVME device. 5. [X13SCH] Fixed SMBIOS type 9 report error slot for X13SCH_SYS SKU.

Release Notes from Previous Release(s)

1.0 (09/01/2023)

- 1. First release.*