

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	G1SMH
Release Version	01.02.15
Build Date	01/25/2024
Previous Version	01.02.06
Update Category	Recommended
Dependencies	BIOS R1.1
Important Notes	IPMI Image: BMC_SCMAS2600-ROT20-2501MS_20240125_01.02.15_STDsp.bin IPMI Update Package: BMC_SCMAS2600-ROT20-2501MS_20240125_01.02.15_STD.zip Note: IPMI firmware should be updated via IPMI WebGUI.
Enhancements	1. NCSI re-scan and switch were treated as “Failover” during PWRON/PWROFF.
New Features	N/A
Fixes	1. Fixed the issue where ipmitool commands failed to properly route IPv6 addresses configured with SLAAC and DHCPv6. 2. Fixed the issue where power consumption graphs sometimes appeared incorrect. 3. Fixed the issue where the Redfish service validator failed.

Release Notes from Previous Release(s)

01.02.06 (12/13/2023)

Initial Release