

# BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DEG-OAD</b>
<b>Release Version</b>	<b>1.01.06</b>
<b>Build Date</b>	<b>02/09/2024</b>
<b>Previous Version</b>	<b>1.01.04</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<ol style="list-style-type: none"><li><b>(ROT2+): Removed the cmd for BMC golden to NOR.</b></li><li><b>(Delta-Next, PlxUpdate): Support getting plx version by CPLD version.</b></li><li><b>(DeltaNext, PlxUpdate): Implemented Redfish API for PLX updating and plx_update application.</b></li></ol>
<b>Fixes</b>	<ol style="list-style-type: none"><li><b>HBM Fan curve and design spec mismatch.</b></li><li><b>SUM Test case fails: 0030 - Ping BMC IP from SUT with different LAN.</b></li><li><b>(ISU168333): Fix Security State of BMC JTAG/Console event that keeps generating during AC on/off test.</b></li><li><b>Displayed the last digit of the PCIeRetimer FW version.</b></li><li><b>(CPLD): Trapped in an endless loop of backup CPLD Golden.</b></li><li><b>Incorrect CPU overheat message.</b></li><li><b>(GPU): Failed to get H100 GPU info.</b></li><li><b>(Front IO, Fan): Didn't show fan speed of rear fan board on v1.10.</b></li><li><b>(Fan, GPU): Enhanced fan control policy.</b></li><li><b>(Redfish): BMC didn't show AOC card temp sensors.</b></li></ol>