

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPU
Release Version	3.0a
Release Date	1/11/2019
Previous Version	2.1b
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Added support for Purley Refresh platform.2. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v6.0.0.1024.3. Set BMC MAC address to UUID for system without onboard LAN1 or with onboard LAN1 disabled.4. Set PCIe correctable and uncorrectable (non-fatal) error report to disabled by default.5. Set RFC4122 encoding to only be enabled for build time produced by IPMI 1.29 or newer.6. Updated CPU microcode SRV_P_262 for Skylake-SP H0/M0/U0 CPUs.7. Disabled unused SPS ME "CUPS IIO" and "Volumetric Airflow" sensor.8. Added 2933 to memory POR.9. Added support for SATA FLR.10. Added support for Monitor Mwait feature.11. Disabled "tRWSR Relaxation" by default.

New features	N/A
Fixes	<ol style="list-style-type: none"> 1. Fixed problem of setup item "Quiet Boot" staying enabled after flashing BIOS with "Quiet Boot" disabled. 2. Added workaround for GPU P2P low bandwidth. 3. Fixed malfunction of disabling Watch Dog while flashing BIOS under OS. 4. Correct standard NVDIMM ADR time. 5. Fixed CPU PBF(Prioritized Base Frequency) Not working issue

Release Notes from Previous Release(s)

2.1b (10/16/2018)

1. Added SATA FLR support.
2. Added support for Monitor Mwait feature.
3. Updated SPS 4.0.4.393.
4. Updated CPU microcode SRV_P_253 for Skylake-SP H0/M0/U0 stepping CPUs.
5. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v5.5.0.1028.
6. Updated BIOS ACM 1.3.9 and SINIT ACM 1.3.6.
7. Changed Onboard LAN SMBIOS table from type 9 to type 41.
8. Fixed problem of BIOS always retrying boot when Re-Try Boot is Disabled.
9. Fixed malfunction of LEGACY to EFI support.