

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DSC+
Release Version	1.76.09
Release Date	02/12/2020
Previous Version	1.76.02
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1 Improve the system trouble shooting dump speed 2 Update Jarsigner certificate 3 set copyright 2020
New features	1 Support JAVA KVM text copy and paste feature
Fixes	1 IPv6 address cannot be added issue 2 no event if NTP enable and NTP server is not accessed. 3 Fix CD-ROM Image ISO mount with SUM 4 System trouble shooting now support to download Version.txt, Health event log, Maintenance event log, FRU and SMBIOS information 5 CD-ROM Image Issues and Config username Special chars support 6 BMC store factory default option in flash. FW updated with non-

preserve follow factory default option in web

7 Fix IKVM resource is not released

8 The link and power information of Intel SSD can't show on the Web page

9 Some nodes cannot detect BMC IP Gateway at SYS-F619P2-FT-DTP1-TS29T (MBD: X11DPFF-SN)

10 Fix existing user can't modify user name in web page

11 When Hostname too long Web GUI display mess up issue

12 SNMP lost some sensor information

13 failed to update bios built in 2020

14 https port restore fail when restore IPMI config

15 IPMI WEBUI Fan Mode Help description mismatch