

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X9DR3-LN4F+/X9DRi-LN4F+
Release Version	3.61
Build Date	1/10/2020
Previous Version	3.48
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Disabled Java version check.
New features	1. Added unique password. 2. Added enable/disable command for system event log.
Fixes	1. Fixed problem of bind password disappearing after saving on LDAP page. 2. Fixed failure to access IPv6 via https. 3. Fixed issue of the minimum power reading appearing as 0. 4. Increased the number of checks before reporting HDD error in SEL. 5. Fixed issue of Active Directory Time Out allowing "0". 6. Fixed failure of web logout to properly destroy session object. 7. Fixed problem of using update flash firmware killing BMC.