

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	BH12SSi-M25
Release Version	2.2
Release Date	08/26/2021
Previous Version	2.0a
Update Category	Recommended
Dependencies	N/A
Important Notes	BIOS Image: BH12SSiPK1.826 BIOS Update Package: BH12SSiPK1.826.zip
Enhancements	1. Update AGESA MilanPI to 1.0.0.5. 2. Update AGESA RomePI to 1.0.0.C.
New features	N/A
Fixes	Fixed SOL no function on Milan CPU.

Release Notes from Previous Release(s)

2.0a (04/23/2021)

1. Change BIOS revision to 2.0a
2. Update AGESA MilanPI to 1.0.0.1.
3. Update A011 GN B1 microcode 0A001119.
4. Update AGESA RomePI to 1.0.0.A.

2.0 (03/12/2021)

1. Fix SDD NVME and Avago 3108 of AOM-BPNIO-SCEA are not working.
2. Fix cannot boot up Rome CPU.

1.0b (10/23/2021)

1. Updated BIOS version to 1.0b.
2. Updated AMD GPU DID & power reading.

1.0a (06/16/2020)

1. Change BIOS revision to 1.0a.
2. Update AGESA RomePI to 1.0.0.7.
3. Update 8310 SSP-B2 microcode 8301038.
4. Fixed USB doesn't work on IPMI GUI.
5. Auto update P1 slot bifurcation and SATA mode.

1.0 (05/04/2020)

First release.