

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12DPi-N(T)6</b>
<b>Release Version</b>	<b>1.1c SPS: 4.4.4.58</b>
<b>Build Date</b>	<b>08/30/2021</b>
<b>Previous Version</b>	<b>1.1b</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Updated the Intel BKC to 2021_WW32 (KIT #645801), RC, Intel update to BKC to fix general platform issues.</li><li>2. Updated the Intel BKC to 2021_WW32 (KIT #645801), SPS, Intel update to BKC to fix general platform issues.</li><li>3. Updated the Intel BKC to 2021_WW32 (KIT #645801), ACM, Intel update to BKC to fix general platform issues.</li><li>4. Updated the Intel BKC to 2021_WW32 (KIT #645801), SINIT, Intel update to BKC to fix general platform issues.</li><li>5. Updated the Intel BKC to 2021_WW32 (KIT #645801), CPU 606A6 Microcode, Intel update to BKC to fix general platform issues.</li><li>6. Updated the Intel BKC to 2021_WW32 (KIT #645801), Intel VROC UEFI, Intel update to BKC to fix general platform issues.</li></ol>

**Release Notes from Previous Release(s)**

**1.1b (7/20/2021)**

1. Reworked UOL to remove MAC from Type 42.
2. Reworked BIOS Template to conform to version 1.0 of the Whitley template.

**1.1a (6/25/2021)**

1. Updated Intel BKC to 2021\_WW24 (KIT #642595), RC.
2. Updated Intel BKC to 2021\_WW24 (KIT #642595), SPS.
3. Updated Intel BKC to 2021\_WW24 (KIT #642595), ACM.
4. Updated Intel BKC to 2021\_WW24 (KIT #642595), SINIT.
5. Updated Intel BKC to 2021\_WW24 (KIT #642595), CPU 606A6 Microcode.
6. Reworked BIOS Template to match version 1.0.
7. Reworked SUM support.
8. Incremented the Anti-Rollback ID to 2.
9. Fixed PB issues.

**1.1 (4/21/2021)**

1. Updated Intel BKC to WW15'21 (PV), RC.
2. Updated Intel BKC to WW15'21 (PV), SPS.
3. Updated Intel BKC to WW15'21 (PV), 606A4 Microcode.
4. Updated Intel BKC to WW15'21 (PV), 606A5 Microcode.
5. Updated Intel BKC to WW15'21 (PV), 606A6 Microcode.
6. Updated Intel BKC to WW15'21 (PV), BIOS ACM.
7. Updated Intel BKC to WW15'21 (PV), SINIT ACM.
8. Updated Intel BKC to WW15'21 (PV), NVDIMM UEFI HII.
9. Update Intel BKC to WW15'21 (PV), VMD VROC.
10. Reworked BIOS Template to match version 0.9.
11. Reworked SUM Support.
12. Implemented Unique FW Name in OEMFID.
13. Implemented Redfish Boot Options.
14. Implemented Intel Optane DCPMM FW Update.
15. Fixed PB issues.

**1.0a (12/28/2020)**

1. Updated Intel BKC to WW51'20.
2. Reworked BIOS template to match version 0.8.
3. Reworked MCTP.

**1.0 (10/30/2020)**

Initial release.