

IPMI Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DSC-6
Release Version	01.01.05
Build Date	8/3/2021
Previous Version	0.10.14
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Now supports staged and run-time BIOS updates.2. BMC kernel changed from 5.1 to 5.4.
New features	None
Fixes	<ol style="list-style-type: none">1. Fixed hang issue with AST2600 when running DC on/off testing with Red hat 8.3, we found that the eSPI will hang after the system hangs.2. Fixed SUM automation test failure.3. Fixed issue where the sender's address under SMTP cannot be restored.4. Fixed issue where the HD sensor shows "na" with AOC S3916 during AC on/off test.5. Added sensors for U.2 SSD connected directly from the motherboard.6. Fixed mount failure pop up error message, also in the event log.7. Fixed issue when mounting a *.img, it displays wrong file type on Java iKVM Virtual Media.8. Updated invalid FW which will show an MEL message when updating the BIOS and CPLD.9. Fixed iKVM(JAVA plug-in/HTML5) to support IMA file type.10. Fixed Language Change title string, which is not translated.11. Improved PSU initialization code, added delay and retries.