

BMC FW Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPU-6
Release Version	01.01.20
Build Date	5/4/2022
Previous Version	01.01.16
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Improved PSU initialization code, added delay and retries.
New features	N/A
Fixes	Fixed the following issues: 1. Fixed web function where user account can't edit user configurations. 2. Fixed RSC rpm reading. 3. Judgment mechanism for network AOC health status 4. Redfish session leak 5. Inconsistent behavior between BMC and BIOS manual recovery

6. Error message string is blocked when zooming in 100% to 200% under Redfish of Modify alerts menu.
7. Maintenance event log display error at /cgi/op.cgi (config_smtp)
8. S3916L-H161R Sensors N/A During DC ONOFF.
9. [AOC-2UR68G4-i2XT/i4XTS] Serial Number not shown on IPMI WEB GUI
10. Add SNMP type user does not have an asterisk(*) to inform Auth Key and Private Key are required items
11. Language Change title string not translated
12. Created new user on web UI should not get error, even though the user ID is occupied on NoAccess user.
13. Interface should not present "Delete" icon while logged in as "Operator" or "User" privileges account. [138112] ECO-- 15340-- 01.01.16 (02/15/2022) -- Modify password while login "Operator" or "User" privileges account will return Oops error!
14. No GPU found on WEB BMC
15. Redfish API Automation test failure
16. Mount failed pop up error message and Even log are incorrect
17. Mount *.img display wrong file type on Java iKVM Virtual Media
18. Updating invalid FW will show MEL message when update BIOS and CPLD