

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DAi-N6
Release Version	1.4 SPS: 4.4.4.202
Build Date	7/11/2022
Previous Version	1.2b
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Updated Intel BKC to 2022_WW23(KIT #732569). RC2. Updated Intel BKC to 2022_WW23(KIT #732569), SPS3. Updated Intel BKC to 2022_WW23(KIT #732569), ACM4. Updated Intel BKC to 2022_WW23(KIT #732569), SINIT5. Updated Intel BKC to 2022_WW23(KIT #732569), CPU 606A6 Microcode6. Updated Intel BKC to 2022_WW23(KIT #732569), Intel VROC UEFI7. Updated Intel BKC to 2022_WW23(KIT #732569), Intel PMEM UEFI8. Updated Option ROM for Intel I210 Giga LAN UEFI9. Added link retrain per port in BIOS.
New features	None
Fixes	None

Release Notes from Previous Release(s)

1.2b (6/1/2022)

1. FRU Test Case - 113

1.2a (4/19/2022)

1. Rolled back VROC SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012. This fixes a system hang when VMD is enabled.

1.2 (2/07/2022)

1. Updated Intel BKC to 2021_WW52 (KIT #709738), RC
2. Updated Intel BKC to 2021_WW52 (KIT #709738), SPS
3. Updated Intel BKC to 2021_WW52 (KIT #709738), ACM
4. Updated Intel BKC to 2021_WW52 (KIT #709738), SINIT
5. Updated Intel BKC to 2021_WW52 (KIT #709738), CPU 606A6 Microcode
6. Updated Intel BKC to 2021_WW52 (KIT #709738), Intel VROC UEFI
7. Updated Intel BKC to 2021_WW52 (KIT #709738), Intel PMEM UEFI
8. Updated Option ROM for Intel I210 Giga LAN UEFI

1.1b (9/10/2021)

1. Updated Intel BKC to 2021_WW32 (KIT #645801), RC.
2. Updated Intel BKC to 2021_WW32 (KIT #645801), SPS.
3. Updated Intel BKC to 2021_WW32 (KIT #645801), ACM.
4. Updated Intel BKC to 2021_WW32 (KIT #645801), SINIT.
5. Updated Intel BKC to 2021_WW32 (KIT #645801), CPU 606A6 Microcode.

1.1a (8/9/2021)

1. Updated Intel BKC to 2021_WW24 (KIT #642595), RC.
2. Updated Intel BKC to 2021_WW24 (KIT #642595), SPS.
3. Updated Intel BKC to 2021_WW24 (KIT #642595), ACM.
4. Updated Intel BKC to 2021_WW24 (KIT #642595), SINIT.
5. Updated Intel BKC to 2021_WW24 (KIT #642595), CPU 606A6 Microcode.
6. Added SMC DIMM bar code information to SMBIOS type 17 serial number field.
7. Fixed failure of AC on/off test in some conditions.

1.1 (4/30/2021)

1. Updated Intel BKC to WW17'21 (PV), RC.
2. Updated Intel BKC to WW17'21 (PV), SPS.
3. Updated Intel BKC to WW17'21 (PV), 606A4 Microcode.
4. Updated Intel BKC to WW17'21 (PV), 606A5 Microcode.
5. Updated Intel BKC to WW17'21 (PV), 606A6 Microcode.

6. Updated Intel BKC to WW17'21 (PV), BIOS ACM.
7. Updated Intel BKC to WW17'21 (PV), SINIT ACM.
8. Updated Intel BKC to WW17'21 (PV), NVDIMM UEFI HII.
9. Updated Intel BKC to WW17'21 (PV), VMD VROC.

1.0a (3/18/2021)

1. Updated Intel BKC to WW11'21.