

IPMI Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DSC-6
Release Version	01.01.08
Build Date	7/8/2022
Previous Version	0.01.05
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none">1. Fixed: Syslog did not properly show error messages after disabling and reenabling2. Fixed: JAVA iKVM session will reconnect when executing "IKVM Reset". The iKVM reset does not work when launching IKVM via JAVA