

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DEG-QT
Release Version	1.00.23
Release Date	08/21/2023
Build Date	08/21/2023
Previous Version	1.00.10
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	1.[156774] "ECO -- 21386 -- 01.00.13 (2023/03/27) -- WEB -- Invalid sensor name." 2.[151493] "I2C re-mapping is Fail" 3.[152234] ECO -- 21386 -- 01.01.08 -- [MEL] No related MEL when setup Active Directory 4.[157111] BMC -- New Version displayed in WebGUI is incorrect when updating BIOS after Seamless Upgrade 5.[158276] Redfish Hostname special characters support

	<p>6.[158355] ECO-1386-01.00.16 (06/05/2023)-Function] Syslog packet not fol low RFC3164.</p> <p>7.[158352] ECO—21386—01.00.16 (06/05/2023)—[MEL-0036] format not quite match with Spec definition.</p> <p>8.[158783] Redfish Automation test failed (w/ 8 failures.)on firmware v01.00.18</p> <p>9.[159173] STD -- 17212 ? 01.01.01? [Security] Error format reply message at X13 and X12 redfish (/redfish/v1/AccountService/Accounts/{num})</p> <p>11.[159950] IPMI ECO 33 Failed cases on Redfish automation.</p> <p>12.[160826] The GPU temp is going high by SRMS</p>
--	---

Release Notes from Previous Release(s)

<p>1.00.10 (02/24/2023)</p> <ol style="list-style-type: none"> 1. [IPMI 01.00.08 ECO] SATC Redfish test failed. 2. [IPMI 01.00.08 ECO] SMTP and SNMP can't receive some of SEL 3. [IPMI 01.00.09 ECO] There are no "Thermal trip " event log." 4. BMC Web Inventory Firmware page is not consistent with other project. 5. [152009] (X13DEG3.130_Signed , auto) Check Seamless Upgrade fail due to can't get correct version <p>1.00.02 (11/25/2022)</p> <ol style="list-style-type: none"> 1. First Release
--